

1075 Providence Highway Sharon, MA 02067 Tel: 781.784-1400

Fax: 781.784-1405 www.metalbellows.com

June 10th, 2025

Quality Alert – Increased Quality Issues Related to Burrs and Dimensional Non-Conformities

Dear Supplier

We are issuing this Quality Alert to bring attention to a recent **increase in quality issues** observed with incoming parts. The primary concerns are:

- Presence of burrs on machined and threaded features
- **Dimensional non-conformities**, including thread features outside of specification.

To support alignment on our expectations, we are including a copy of **Engineering Specification ES 1018**, which outlines requirements for **burr-free parts** and **thread specifications**. It is critical that your team **reviews this specification thoroughly**. If there are any questions or clarification needed, please **reach out promptly** to our Supplier Quality Engineer.

Please note:

- Non-conforming parts will be returned, which will negatively impact your on-time delivery performance.
- Repeated quality issues will also impact your **overall supplier quality score** and may affect future sourcing decisions.

Action Required:

- 1. Review ES 1018 internally and confirm understanding.
- 2. Inspect all outgoing parts for burrs and dimensional compliance.
- 3. Contact our Supplier Quality Engineer immediately with any concerns or questions.

We appreciate your attention and commitment to continuous improvement.



Charlie Damon

Supplier Quality Engineer 1075 Providence Hwy | Sharon, MA 02067

Office: 781-302-1218

<u>Charlie.Damon@metalbellows.com</u> -<u>www.metalbellows.com</u>



